









Confidential Home Inspection Report

Actual Inspection Report Ramsey MN 55303

763.000.0000

May 7th 2009

By
Michael J Foschi
Fair and Square Construction Services - HOME INSPECTION
14408 Tungsten Way
Ramsey, Minnesota
763.442.4865

A Proud Member of the Best Inspectors Network™

Fair and Square Construction Services General Information

763.000.0000

Ochiciai illioi	mation	703.000.0000		
Building Descr	iption			
Attribute	Description / Type	Address / Comments		
Age (approximate)	5-10 years	Actual Inspection Report		
Area (approximate)	1550 square feet	Ramsey, MN, 55303		
		Date of Inspection: May 7th 2009		
Building type	Single family, tri-level			
	✓ Single Family Townhome			
	Single family, ranch			
	See comments			
Construction	Not applicable			
Conditaction	✓ Frame			
	Brick			
	See comments			
Additional Build	ding Description/ Comment	S		
Home Direction: View	ved from front			
Nice two level Townho	ome in a great neighborhood setting in F	Ramsey.		
Solid structure with no	major defects found. Items in need of	attention are of no significant dollar amount.		
Please take note of ar	ny <mark>Safety items</mark> and act accordingly to u	pdate or repair as soon as practicable.		
Townhome exteriors a	are not included on inspection report but	in general observation; siding, roofing, and grounds appeared to be		
in favorable condition				
Note: red boxes or wri	ting throughout this report indicating da	mage or items marked as needing repair may result in further		

Client Information

damage or may present a safety hazard if not repaired.

Name	Actual	Inspection Report
Address		
Phone(s)		E-mail
Buyer's agent	Joel Friday	
Phone(s)	612.868.6287	E-mail joel@joelfridayhomes.com
Seller's agent		
Phone(s)		E-mail
Lockbox/Other		

Notes/ Special Instructions

Direction: From Front



Weather at time of inspection

Temperature	Start Time	General Conditions
65° Fahrenheit	8:30am	Clear

Utilities 763.000.0000

Under Ground Electric Service

	l = In	spec	ted/	OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
	NI	NA	R	F	Item Comments Electric Under ground service 110/220		em ublic utility	
~					Natural gas Outside front of unit	Pι	ublic utility	
		•			Back-up gas	Pt	ublic utility	
		✓			Propane	Pu	ublic utility	
		✓			Water	Pt	ublic utility	
		✓			Deep well	Pr	ivate Utility	
		✓			Point well	Pr	ivate Utility	
		✓			Generator	Pr	ivate Utility	
		•			Solar	Pr	ivate Utility	
		<u>~</u>			Septic	Pr	ivate Utility	

Photos and Additional Comments



Electric Meter



Garage - Two Car Attached

763.000.0000

I = Inspected/OK			ted/	OK	NI = Not Inspected	A = Not Applicable	R = Repair	F = Failure/Safety
ı	NI	NA	R	F	Item Comments	С	ondition	
					Siding			
				$\overline{}$	Faccion coffito deino			
Ш		Ш	Ш	ш	Fascia, soffits, trim			
Ш		Ш	Ш	Ш	Service Door(s)			
<u> </u>								
Ш		Ш	Ш	Ш	Window(s)			
~	Ш	Ш	Ш	Ш	Overhead door(s)			
					Locked - Do not use opener until	lock is removed		
~	ш	Ш	ш	Ш	Safety eye(s)			
V					Water faucets			
					Window wells, crawl space vents			




Attic - Viewed From Ladder @ Scuttle

763.000.0000

I = Inspected/OK	NI = Not Inspected NA = Not Applicable R = Repair F = Failure/Safety
I NI NA R F	Item Condition Comments
	Access Insulation
	Moisture
	Stains
	Rafters
	Trusses Not viewable - Covered with insulation
V	Ventilation Turtle roof vents - Gable vents - Soffit ventilation
	Attic baffles



	I = Inspected/OK			ЭK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
	NI	NA	R	F	Item Comments Location Enclosed Natural Gas Fireplace	C	tem Condition Ving room heck	
		•			Clearance			
~					Firebox Viewed thru door			
		✓			Flue damper			
		✓			Flue			
		•			Refractory			
	✓				Heatilator			
•					Hearth (firebox floor)			
•					Doors			
~					Mantle			



Bedrooms 763.000.0000

	l = In	spec	ted/	OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
ı	NI	NA	R	F	Item Comments	lt	em	
~					Master bedroom	Do	oors and windows	
~	Ш	Ш	ш	Ш	Master bedroom	Flo	oor	
	Ш	Ш		Ш	Master bedroom	W	alls and ceiling	
~					Master bedroom	CI	loset	
	Ш	Ш	Ш	Ш	Master bedroom	El	ectrical and lighting	
Ш	Ш	Ш		✓	Bedroom 2		oors and windows	
					Large cracked window in 2nd	bedroom		
~	Ш	Ш	Ш	Ш	Bedroom 2	Flo	oor	
~	Ш	Ш	Ш	Ш	Bedroom 2	W	alls and ceiling	
~		Ш	Ш	Ш	Bedroom 2	CI	loset	
~	Ш	Ш	Ш		Bedroom 2	El	ectrical and lighting	




Bedrooms 763.000.0000

	l = In	spec	ted/0	OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	Ite	em	
~					Bedroom 3	Doo	ors and windows	
V					Bedroom 3	Floo	or	
✓					Bedroom 3	Wal	lls and ceiling	
V					Bedroom 3	Clos	set	
V					Bedroom 3	Elec	ctrical and lighting	
		✓			Bedroom 4	D00	ors and windows	
		•			Bedroom 4	Floo	or	
		✓			Bedroom 4	Wal	lls and ceiling	
		~			Bedroom 4	Clos	set	
		✓			Bedroom 4	Elec	ctrical and lighting	
Pho	nt ne	and	Δda	ditio	nal Comments			
1 110	103	and	Add	aitio	nai Comments			

Rooms - Utility Area

I = Inspected/OK	NI = Not Inspected	NA = Not Applicable	R = Repair F = Failure/Safety
I NI NA R F	Item Comments Utility room		em oors and windows
	Burst pipe to faucet in garage		
	Use drop-down to select a room	Flo)OI
	Use drop-down to select a room	Wa	alls and ceilings
	Use drop-down to select a room	Clo	oset
	Use drop-down to select a room	Ele	ectrical and lighting
	Use drop-down to select a room	Do	ors and windows
	Use drop-down to select a room	Fic	oor .
	Use drop-down to select a room	Wa	alls and ceilings
	Use drop-down to select a room	Cic	oset
	Use drop-down to select a room	Ele	ectrical and lighting



©1999-2009 MSI International, Inc. **Best Inspectors. Net**TM

Bathrooms - 1/2 Down - Full Master Up

763.000.0000

	= In	spec	ted/0	ЭK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	lte	em	
~					Master bathroom	То	ilet	
~	Ш	Ш	Ш	Ш	Master bathroom	Sh	lower and bathtub	
~	Ш	Ш	Ш	Ш	Master bathroom	Plu	umbing	
	П			П	Master bathroom	Ele	ectrical and lighting	
			_				0 0	
~	Ш	Ш	Ш	Ш	Master bathroom	Wi	indows, walls, doors	, floor, ceiling
			П	П	Bathroom 2	To	ilet	
				_		<u> </u>		
Ш	Ш		Ш	Ш	Bathroom 2	Sh	lower and bathtub	
~	П		П	П	Bathroom 2	Plu	umbing	
							<u> </u>	
	_							
	Ш	Ш	Ш	Ш	Bathroom 2	Ele I protected - Protection is in Mast	ectrical and lighting	
					Outlet should be marked of o	protected - Protection is in mast	er batti upstalis	
<u>~</u>	П		П		Bathroom 2	Wi	indows, walls, doors	, floor, ceiling
Б.			۸ ۱	11.41				
Pho	tos	and	Add	oitic	nal Comments			

©1999-2009 MSI International **Best Inspectors. Net**TM

Kitchen 763.000.0000

	= In	spec	ted/	OK	NI = Not Inspected NA	= Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	Ite	em	
~					Kitchen	Ca	binets	
~					Kitchen	Co	ounter tops and sink	
~	Ш	Ш	Ш	Ш	Kitchen	Plu	umbing	
~	Ш	Ш	Ш	Ш	Kitchen	Ele	ectrical and lighting	
	_							
~	Ш	Ш	Ш	Ш	Kitchen	Wi	indows and doors	
~	Ш		Ш	Ш	Kitchen	Wa	alls and ceiling	
	_							
~	Ш	Ш	Ш	Ш	Kitchen	Flo	oor	
~	Ш	Ш	Ш	Ш	Kitchen	Plu	umbing	
~	Ш	Ш	Ш	Ш	Kitchen	Ele	ectrical and lighting	
	_							
Ш		Ш	Ш	_	Kitchen Small puddle on floor - Water line ha	Re	frigerator	
					Small puddle on floor - water line na	s slow leak		
Pho	tos	and	Ad	ditio	nal Comments			

Utility Room 763.000.0000

	l = In	spec	ted/0	OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	Ite	em	
					Utility room	Ca	binets	
		~			Utility room	Co	unter tops and sink	
		Ш	Ш	Ш	Utility room	Plu	umbing	
ļ.—,			<u> </u>					
~	Ш	Ш	Ш	Ш	Utility room	Ele	ectrical and lighting	
Ш	Ш		Ш	Ш	Utility room	Wi	indows and doors	
			<u> </u>					
_	ш	ш	Ш	Ш	Utility room	Flo	oor	
_	Ш	Ш	Ш	Ш	Utility room	Wa	alls and ceiling	
Ш	Ш		Ш	Ш	Utility room			
_								
	Ш		Ш	Ш	Utility room			
	Ш		Ш	Ш	Utility room			

Photos and Additional Comments



Air gap should be placed between water softener hose and floor drain



Change filter on a monthly basis for maximum efficiency of both furnace and AC



Plumbing - 3/4 Copper/Plastic/Pex

763.000.0000

	I = Inspected/OK				NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	С	Condition	
~					Meter and Main shut-off valve(s)			
					Water and gas shut off valves ar	e in utility room		
~				П	Gas meter			
					Outside on meter and in utility ro	oom		
~					Vents			
_	_			_				
~	Ш	Ш	Ш	Ш	Drainage			
~	Ш		Ш	Ш	Distribution piping			
~	Ш	Ш	ш	Ш	Fittings			
~	Ш	Ш	ш	Ш	Valves			
					Visually inspected valves - Did n	ot operate any valves		
			Ш	Ш	Whole house filter			



	I = Inspected/OK				NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
I	NI	NA	R	F	Item Comments	C	Condition	
~					Water piping, valves, and fittings	1		
~	Ш	Ш		Ш	Gas piping, valves, and fittings			
~	Ш	Ш	Ш	Ш	Temperature/Pressure Relief Val	ve		
~	Ш	Ш	Ш	Ш	Drain			
					No knob on drain			
	Ш	~	Ш		Enclosure and pan			
	_							
~	Ш	Ш	ш	Ш	Controls			
~	Ш	Ш	ш	Ш	Age	5-	-10 years	
~	Ш			Ш	Capacity	40	US Gallons	

Photos and Additional Comments




©1999-2009 MSI International **Best Inspectors. Net**TM

Heating - Forced Air Natural Gas


763.000.0000

I = Inspected/OK				OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
ı	NI	NA	R	F	Item Comments	(Condition	
~	П	П	П	П	Gas piping, valves, and fittings			
		_	_					
					Heat exchanger			
		_	_		Not visible - enclosed			
	П				Blower			
	_	_						
V	ш	ш	ш	ш	Controls			
		✓			Humidifier			
<u> </u>	_							
V	Ш	Ш	Ш	Ш	Flue			
V	ш	ш	ш	ш	Age	5	i-10 years	
✓	Ш		Ш	Ш	Output Capacity	8	0000 BTU	



	l = lr	spec	ted/	OK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
	NI	NA	R	F	Item Comments	C	Condition	
~					Condenser coil/ housing			
_				_				
~		Ш	Ш	Ш	Evaporator coil			
					Enclosed - not viewable			
~					Fan			
_				_				
~		Ш	Ш	Ш	Controls			
~		Ш	Ш	Ш	Refrigerant lines			
	ш	Ш	Ш	Ш	Output Capacity	80	0000 BTU	
~		Ш	Ш	Ш	Age	5-	10 years	
~			Ш	ш	General condition/ comments			

Photos and Additional Comments



AC condenser cabinet and disconnect




©1999-2009 MSI International **Best Inspectors. Net**TM

Electrical 100 amp Main Panel

763.000.0000

	l = Inspected/OK				NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
ı	NI	NA	R	F	Item Comments	С	condition	
V					Service entrance cable/conduit			
_	Ш	ш	Ш	Ш	Main panel	10	0 amp	
					In garage			
~				П	Main breaker/disconnect			
		_			100 amp			
~	Ш			Ш	Made electrode - Water line			
	Ш	Ш	Ш	Ш	Made electrode - Ground rod			
					Ground rod not visible			
V	Ш	ш	Ш	Ш	Branch circuits			
Ш	Ш		Ш	Ш	GFCI breakers			
V	Ш	Ш	Ш	Ш	AFCI breakers			

Photos and Additional Comments



©1999-2009 MSI International *Best I nspectors . Net*TM

Electrical 763.000.0000

I = Inspected/OK				ϽK	NI = Not Inspected	NA = Not Applicable	R = Repair	F = Failure/Safety
ı	NI	NA	R	F	Item Comments	C	Condition	
	V				CATV			
		П	П	П	Telephone			
		П			Security system			
	Ľ	ш		ш	Coounty System			
Y	Ш	Ш	Ш	Ш	Smoke detector(s)			
Ш	Ш	Ш	<u>~</u>	<u> </u>	Carbon monoxide detector(s)	mend installation near bedrooms	s ner local building	code and one in utility room
					no detectors present Recom	mena installation flear bear come	s per local ballang	code and one in dainly room
		•			Subpanel(s)			
П	П	~	П	П	Lightning arrestor(s)			
					Shed/ outbuilding			
	ш	Ľ		ш	Oned, cateurang	ļ		
Pho	tos	and	Δda	ditio	nal Comments			
FIIO	103	anu	Aut	aitio	nai Comments			
@4000	2000 M	21 Intorn	ational	Roct	I nspectors . N et™			

This document was created with Win2PDF available at http://www.win2pdf.com. The unregistered version of Win2PDF is for evaluation or non-commercial use only. This page will not be added after purchasing Win2PDF.